
1	Robust Sensor for Extended Autonomous Measurements of Surface Ocean Dissolved Inorganic
2	Carbon
3	
4	Andrea J. Fassbender, <sup>*,†</sup> Christopher L. Sabine, <sup>‡</sup> Noah Lawrence-Slavas, <sup>‡</sup> Eric H. De Carlo, <sup>§</sup>
5	Christian Meinig, <sup>‡</sup> and Stacy Maenner Jones <sup>‡</sup>
6	
7	<sup>†</sup> University of Washington, School of Oceanography, Box 357940, Seattle, Washington 98105,
8	United States
9	<sup>‡</sup> National Oceanic and Atmospheric Administration, Pacific Marine Environmental Laboratory,
10	Seattle, Washington 98115, United States
11	<sup>§</sup> University of Hawai'i at Manoa, School of Ocean and Earth Science and Technology, Honolulu,
12	Hawaii 96822, United States
13	
14	*Phone: (206) 526-6208; fax: (206) 526-6744; e-mail: andrea.fassbender@noaa.gov (A.J.F.).
15	
16	Pages: 4
17	Figures: 2
18	Tables: 1
19	
20	
21	
22	
23	

24 Supporting Information

25

- 26 **10-port Valve Flow Pathways**
- 27



28


Figure S1. 10-port valve flow pathways used to control sample and acid additions. The sample and acid loops are filled during separate sequences of the measurement when the valve is in position A. The valve is then switched to position B to inject the fluid into the equilibration chamber. Loops are not drawn to scale.

33

34

- 35
- 36
- 37





40

Figure S2. Diagram of the Seattle Aquarium flow-through system. Water from ~12m depth was
pumped through a valve manifold that fed into the three flow-through pathways depicted.
Discrete bottle samples were collected from a valve on the manifold for later coulometric DIC
analysis.

45

## 46 Honolulu, HI Deployment Drift Correction

47

In December of the Honolulu, HI deployment,  $xCO_2$  measurements began to drift with time. 48 After thorough review of the raw LI-820 diagnostic data and multiple discussions with a 49 technician at LICOR, we identified the source of the drift to be an interference (debris) in the 50 optical chamber. The drift was initially identified from the increasing  $xCO_2$  values in the field 51 and confirmed as an infrared detector malfunction during post-deployment calibration in the 52 laboratory. The DIC bottle samples were not used in this correction or for justifying the 53 54 correction. The adjustment was made simply for  $xCO_2$  quality control purposes prior to DIC calculation. This correction was unique to the Hawaii deployment and is not part of the usual 55 post-deployment quality control. 56

57

58 Due to the strong relationship between the LICOR response and temperature (which is why the sensor is calibrated prior to every measurement), and the nature of the field malfunction, we 59 applied a small non-linear temperature correction to account for temperature interferences 60 resulting from the detector drift issue. Again, this correction was to account for a temporary issue 61 with the LICOR detector used on this one deployment and would not normally be part of the 62 system calculations. This modest correction had an average influence of 1.4 ppm on the  $xCO_2$ 63 values and improved the overall DIC measurement accuracy from  $6\pm14 \mu mol \text{ kg}^{-1}$  to  $1\pm11 \mu mol$ 64  $kg^{-1}$ . 65

66

## 67 Honolulu, HI Calculated vs. Direct Measurement Comparisons

**Table 1.** Mean and standard deviation of the difference between calculated and measured values for  $xCO_2$ , pH and DIC. Differences between bottle DIC and the calculated and MADIC measured DIC values are also given. May 2014 data are omitted from these computations due to a SAMI<sup>2</sup>-pH sensor clog.

7	r
/	2

	Mean Difference	StDev.
$xCO_{2 Calc} - xCO_{2 Meas}$	-3	9
$pH_{Calc}-pH_{Meas}$	0.006	0.009
$DIC_{Calc} - DIC_{Meas}$	-27	43
$DIC_{Bottle} - DIC_{Calc}$	21	37
$DIC_{Bottle} - DIC_{Meas}$	1	11

73