




$H = 0, d/L = 0.76$




$H = 0, d/L = 0.96$




$H = 0, d/L = 1.18$




$H = 0, d/L = 1.36$




$H = 0, d/L = 1.56$




$H = 0, d/L = 1.77$




$H = 0, d/L = 1.97$




$H = 0, d/L = 2.17$




$H = 0, d/L = 2.37$




$H = 0, d/L = 2.58$




$H = 0, d/L = 2.78$




$H = 0, d/L = 2.98$




$H = 0, d/L = 3.18$




$H = 0, d/L = 3.38$




$H = 0, d/L = 3.59$




$H = 0, d/L = 3.79$




$H = 0, d/L = 3.99$




$H_A = -7, d/L = 0.76$




$H_A = -7, d/L = 0.96$




$H_A = -7, d/L = 1.18$




$H_A = -7$, $d/L = 1.36$




$H_A = -7$, $d/L = 1.56$




$H_A = -7$, $d/L = 1.77$




$H_A = -7$, $d/L = 1.97$




$H_A = -7$, $d/L = 2.17$




$H_A = -7$, $d/L = 2.37$




$H_A = -7$, $d/L = 2.58$




$H_A = -7$, $d/L = 2.78$




$H_A = -7$, $d/L = 2.98$




$H_A = -7$, $d/L = 3.18$




$H_A = -7, d/L = 3.38$




$H_A = -7, d/L = 3.59$




$H_A = -7, d/L = 3.79$




$H_A = -7, d/L = 3.99$




$H_A = -14, d/L = 0.76$




$H_A = -14, d/L = 0.96$




$H_A = -14, d/L = 1.18$




$H_A = -14, d/L = 1.36$




$H_A = -14, d/L = 1.56$




$H_A = -14, d/L = 1.77$




$H_A = -14$, $d/L = 1.97$




$H_A = -14$, $d/L = 2.17$




$H_A = -14$, $d/L = 2.37$




$H_A = -14$, $d/L = 2.58$




$H_A = -14$, $d/L = 2.78$




$H_A = -14, d/L = 2.98$




$H_A = -14, d/L = 3.18$




$H_A = -14, d/L = 3.38$




$H_A = -14, d/L = 3.59$




$H_A = -14, d/L = 3.79$




$H_A = -14, d/L = 3.99$




$H_B = -7, d/L = 0.76$




$H_B = -7, d/L = 0.96$




$H_B = -7, d/L = 1.18$




$H_B = -7, d/L = 1.36$




$H_B = -7, d/L = 1.56$




$H_B = -7, d/L = 1.77$




$H_B = -7, d/L = 1.97$




$H_B = -7, d/L = 2.17$




$H_B = -7, d/L = 2.37$




$H_B = -7, d/L = 2.58$




$H_B = -7, d/L = 2.78$




$H_B = -7, d/L = 2.98$




$H_B = -7, d/L = 3.18$




$H_B = -7, d/L = 3.38$




$H_B = -7$, $d/L = 3.59$




$H_B = -7$, $d/L = 3.79$




$H_B = -7$, $d/L = 3.99$




$H_B = -14$, $d/L = 0.76$




$H_B = -14$, $d/L = 0.96$




$H_B = -14, d/L = 1.18$




$H_B = -14, d/L = 1.36$




$H_B = -14, d/L = 1.56$




$H_B = -14, d/L = 1.77$




$H_B = -14, d/L = 1.97$




$H_B = -14, d/L = 2.17$




$H_B = -14, d/L = 2.37$




$H_B = -14, d/L = 2.58$




$H_B = -14, d/L = 2.78$




$H_B = -14, d/L = 2.98$




$H_B = -14, d/L = 3.18$




$H_B = -14, d/L = 3.38$



$H_B = -14, d/L = 3.59$



$H_B = -14, d/L = 3.79$



$H_B = -14, d/L = 3.99$

