

Figure S1. Dependence of P3BT/PMMA conductivity on P3BT content in the composites as measured with 4-probe method (solid square) and 2-probe method (open square), respectively.




Figure S2. Dependence of σ/φ of P3BT/PMMA composite on P3BT content (φ) in the composites as measured with 4-probe method (solid square) and 2-probe method (open square), respectively.




Figure S3. Dependence of P3BT/regiorandom P3HT (RRa-P3HT) conductivity on P3BT content in the composites as measured with 4-probe method (solid square) and 2-probe method (open square), respectively.